MEASURE WITH PRECISION

www.sew.com.tw

5F., NO.105, Jhongcheng Rd., Tucheng Dist., New Taipei City 23674, Taiwan (R.O.C.) TEL: 886-2-22681528 FAX: 886-2-22681529 e-mail: sales@sew.com.tw



Analogue Insulation Tester



FEATURES

- High quality Taut Band movement.
- Three insulation test voltages(DC) : 250V, 500V, 1000V.
- Two continuity test on "low ohms" : $3\Omega \& 500\Omega$.
- AC voltmeter with linear scale up to 600 Vac.
- 200mA short circuit current for continuity.
- 1mA test current on insulation test at nominal voltage.
- Automatic discharge of capacitive and inductive circuit with charge stored in the circuit under test.
- Live warning and display of external voltage presence.
- Fuse, air gap, crowbar and overload protected.
- On line battery monitoring shows if battery is ok.
- Manual zero ohm adjustment.
- Low battery consumption.
- Mirror scale.
- Push and turn locking switch for continuous and hand free testing.
- Supplied with high quality test leads.
- BS 16th edition.

SPECIFICATIONS

Insulation Resistance			
Test voltage (DC V)	250V	500V	1000V
Output voltage on open circuit	Rated test voltage +10%		
Measuring ranges	0-100ΜΩ	0-200ΜΩ	0-400ΜΩ
Mid-scale value	1ΜΩ	2ΜΩ	4ΜΩ
Scale multiplier	×1/2	×1	×2
Accuracy	± 5% of indicated value		
Output short-circuit current	Approx. 1.2mA		
Continuity			
Measuring ranges	3Ω / 500Ω		
Zero Ω adjustment by knob	\checkmark		
Output short-circuit current	≥ 200 mA		
Accuracy	± 1.5% of scale length		
AC Voltage			
Range	0-600V AC		
Accuracy	± 3% of scale length		
General			
Voltage warning	Warning light circuit live lit from 90Vdc / 70Vac, Buzzer beep from 24Vac/dc		
Dimensions	221(L) × 110(W) × 56.8(D)mm		
Weight (battery included)	Approx. 600g		
Power source	1.5V (AA) × 6		
Safety standard	EN 61010-1 CAT III 600V EN 61326-1		
Accessories	Instruction manual Tes Fuse (0.5A/690V, 6×32m Batteries Carry case	,	Hand strap