




HIGH PRECISION DIGITAL HEIGHT GAGES




power supplied by charge pal



data transmitted to Excel without software;
short press the foot switch to transmit data,
long press to zero



1155-505



- High stability, high precision, high response speed (5000mm/s)
- High brightness LED display
- Ceramic base flatness: 1 μ m

| Code | Range | Resolution | Accuracy (20°C) | Measuring force | Output | Power supply |
|----------|--------|--|-----------------|-----------------|--------|----------------------------------|
| 1155-505 | 0~50mm | 0.5 μ m/0.00002" (can switch to: 1 μ m/0.00005") | 1.5 μ m | 0.8~1.2N | USB | 5V/1A (adapter or charge pal) |
| 1155-510 | 0~50mm | 0.1 μ m/0.000005" (can switch to: 1 μ m/0.00005") | 1 μ m | 0.8~1.2N | USB | 5V/1A (adapter or charge pal) |

STANDARD DELIVERY

| | |
|-----------|------|
| Main unit | 1 pc |
|-----------|------|

OPTIONAL ACCESSORY

| | |
|--|------------|
| Contact point | code 6282 |
| Charge pal | 1155-5-POB |
| Data output cables (including foot switch) | 1155-5-FOS |